



CCSD 89 technology replacement costs

This is the cost charged to families for replacement or repair of district technology devices. If you have questions, please contact your building principal or the district's Technology Office.

Model	Item	Repair cost
Dell 3110 2-in-1	Whole-unit replacement	\$330.00
Dell 3110 2-in-1	Touch screen	\$219.00
Dell 3110 2-in-1	Keyboard	\$99.00
Dell 3110 2-in-1	Palm rest with camera	\$129.00
Dell 3110 2-in-1	Bottom cover	\$109.00
Dell 3110 2-in-1	Hinge(s)	Vendor quote required
Dell 3110 2-in-1	65W USB-C charger	\$38.95
Dell 3110 2-in-1	Carrying case	\$16.00
Dell 3100 2-in-1	Whole unit replacement	\$330.00
Dell 3100 2-in-1	LCD touch screen	\$209.00
Dell 3100 2-in-1	Keyboard	\$99.00
Dell 3100 2-in-1	Palm rest with camera	\$129.00
Dell 3100 2-in-1	Bottom cover	\$109.00
Dell 3100 2-in-1	Hinges	Vendor quote required
Dell 3100 2-in-1	65W USB-C charger	\$38.95
Dell 3100 2-in-1	Carrying case	\$16.00
iPad (6th Gen)	Whole unit replacement	\$299.00
iPad (6th Gen)	Digitizer (glass)	\$109.00
iPad (6th Gen)	Digitizer (glass) + LCD	\$169.00
iPad (6th Gen)	Headphone jack replacement	\$89.00
iPad (6th Gen)	Lightning port replacement	\$109.00
iPad (6th Gen)	USB-C charger with lightning cable	\$38.00
iPad (6th Gen)	Apple pencil (first generation)	\$99.00
iPad (7th Gen)	Whole unit replacement	\$299.00
iPad (7th Gen)	Digitizer (glass)	\$149.00
iPad (7th Gen)	Digitizer (glass) + LCD	\$259.00
iPad (7th Gen)	Headphone jack replacement	\$89.00
iPad (7th Gen)	Lightning port replacement	\$109.00
iPad (7th Gen)	USB-C charger with lightning cable	\$38.00
iPad (7th Gen)	Apple pencil (first generation)	\$99.00
iPad (9th Gen)	Whole unit replacement	\$299.00
iPad (9th Gen)	Digitizer (glass)	\$149.00
iPad (9th Gen)	Digitizer (glass) + LCD	\$259.00
iPad (9th Gen)	Headphone jack replacement	\$109.00
iPad (9th Gen)	Lightning port replacement	\$89.00
iPad (9th Gen)	USB-C charger with lightning cable	\$38.00
iPad (9th Gen)	Apple pencil (first generation)	\$99.00